

WALTERSCHEID

PTO Shaft and Clutch Servicing – Winter Special

Contractors using our winter servicing are having far fewer in season failures caused by faulty worn parts.

Walterscheid NZ Ltd has all the tools and expertise for servicing PTO shafts and clutches (currently about 160 cam clutches are serviced annually from all over NZ).

The shafts are cleaned and inspected, and parts replaced where necessary. The clutches are dismantled, cleaned and inspected, worn parts replaced, reassembled and then tested on a German made computerised torque bench, with adjustments being made where necessary.

Take advantage of our special Winter* rates:

Servicing: \$50.00/hr +GST (\$70.00/hr +GST in season rate)

Clutch testing: \$25.00 +GST per clutch

**Winter rates apply from April 1st until October 1st.*

'It is not the cost of the breakdown but the cost of being broken down that really costs during the busy season.'


For Genuine Walterscheid with German precision engineering ask your dealer to contact Walterscheid (NZ) Ltd.

Phone +64-7-846 7040 Fax +64-7-846 7041

Email: walterscheid@xtra.co.nz www.walterscheid.co.nz

63 Colombo Street, Hamilton

We deal with dealers from Kaitia to Invercargill.



WALTERSCHEID

Cramer
Kupplung

**Hitch Systems for the
Agricultural Market**

